

WA-I- 519      Brick Bungalow

1940s

Hagerstown Vicinity

Private

The Brick Bungalow is a one and one-half story, two-bay by three-bay brick structure on a concrete block foundation. It has a gable roof which is slightly flaired to form the roof of the front porch. The roof is covered with asphalt shingles and has a large gable dormer on the front.

The main facade consists of the porch with a large side entrance with ornamented door frame and a four-section window. The property has a rectangular plan and appears to have been built in the 1940s.

Magi No.

DOE ☐ yes ☐ no

# Maryland Historical Trust

## State Historic Sites Inventory Form

### 1. Name (indicate preferred name)

historic Brick bungalow

and/or common

### 2. Location

street & number west side of Rt. 65, .3 mile south of I-70 ☐ not for publicationcity, town Hagerstown ☒ vicinity of congressional district sixthstate Maryland county Washington

### 3. Classification

Category	Ownership	Status	Present Use
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> occupied	<input type="checkbox"/> agriculture <input type="checkbox"/> museum
<input type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial <input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational <input type="checkbox"/> private residence
<input type="checkbox"/> site	<b>Public Acquisition</b>	<b>Accessible</b>	<input type="checkbox"/> entertainment <input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government <input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial <input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military <input type="checkbox"/> other:

### 4. Owner of Property (give names and mailing addresses of all owners)

name

street &amp; number telephone no.:

city, town state and zip code

### 5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liberstreet & number Washington Street foliocity, town Hagerstown state Maryland

### 6. Representation in Existing Historical Surveys

title

date ☐ federal ☐ state ☐ county ☐ local

depository for survey records

city, town state

## 7. Description

Survey No. WA-I-499 519

### Condition

☐ excellent  
☐ good  
☐ fair

☐ deteriorated  
☐ ruins  
☐ unexposed

### Check one

☐ unaltered  
☐ altered

### Check one

☐ original site  
☐ moved      date of move \_\_\_\_\_

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The brick bungalow is a one and one-half story, two-bay by three-bay brick structure on a concrete block foundation. It has a gable roof which is slightly flaired to form the roof of the front porch. The roof is covered with asphalt shingle and has a large gable dormer on the front. The main facade consists of the porch with a large side entrance with ornamented door frame and a four-section window. The property has a rectangular plan and appears to have been built in the 1940s.

The property is located on the west side of Rt. 65, .3 mile south of I-70. It is situated in a cluster of buildings on  $\frac{1}{4}$  to  $\frac{1}{2}$  acre lots of land that date from the mid-20th century to the present time.

The bungalow is a brick structure on a concrete block foundation. It has an asphalt shingle covered roof and a brick flue at the north gable end. The main facade has a porch with a stick railing and boxed posts. Within the porch is a doorway with a fanlight. On the roof is a large gabled dormer with a three-section window.

There are no significant outbuildings on the property.

## 8. Significance

Survey No. WA-I-~~499~~ 519

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

### Specific dates

### Builder/Architect

check: Applicable Criteria: ☐ A ☐ B ☐ C ☐ D  
and/or

Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G


Level of Significance: ☐ national ☐ state ☐ local

Prepare both a summary paragraph of significance and a general statement of history and support.

This site contains an excellent example of a mid-20th century bungalow. At the present time, its significance is minimal due to its recent date of construction.




WA-I-519  
 Brick Bungalow  
 10425 Sharpsburg Pike (MD 65)  
 Funkstown Quadrangle



1993-94 Aerial Photo



Tax Map 57, p. 142





1. Brick Bungalow WA-I-499 519
2. Washington County, Maryland
3. Joe Getty
4. May 1983
5. Maryland Hist. Trust, Annapolis, Md.
6. East Elevation; camera facing west
7. 1/1